



ACUMEN

INDUSTRIAL HYGIENE INC

1032 IRVING ST. #922 SAN FRANCISCO CA 94122

TEL 415 242 6060 FAX 415 242 6006

WWW.ACUMEN-IH.COM

**Asbestos, Lead, and Hazardous Materials
Pre-demolition Survey Report**

for

**Palo Alto Veterans Administration Hospital
VA PAHCS, Building 23, Gymnasium and Pool**

Acumen Project No. SMG 2801B

December, 2008

Prepared for:

**SmithGroup/The Design Partnership Associate
301 Battery Street, 7th floor
San Francisco, CA**

This report was prepared by:

Mark T. Schmidt, CAC, CDPH, REA
Project Manager

This report was reviewed by:

Paul M. Spillane, CIH, CAC
Principal Industrial Hygienist

Table of Contents

| | | |
|------------|--------------------------------------|----------|
| 1.0 | Introduction | 3 |
| 2.0 | Summary of Investigation..... | 3 |
| 3.0 | Document Review | 4 |
| 4.0 | Findings and Discussion | 5 |
| 5.0 | Summary of Findings | 6 |
| 5.1 | ASBESTOS RELATED FINDINGS | 6 |
| 5.2 | LEAD RELATED FINDINGS | 7 |
| 6.0 | Hazardous Materials | 7 |
| 7.0 | Recommendations | 8 |
| | Limitations | 9 |

APPENDIX A CHAIN OF CUSTODIES AND ANALYTICAL REPORTS

APPENDIX B PREVIOUS REPORTS

APPENDIX C SITE PHOTOGRAPHS

APPENDIX D SAMPLE LOCATION DRAWINGS

1.0 Introduction

The purpose of this letter is to report the findings of an asbestos and lead survey conducted at the above referenced facility by Acumen Industrial Hygiene, Inc. (Acumen). It is understood that Building 23 is scheduled for demolition. Mr. Mark T. Schmidt, Certified Asbestos Consultant (CAC) #99-2641, and California department of Public Health Lead Inspector/Assessor #5838 conducted the investigation at the building on November 3, 2008. The inspection was limited to accessible building areas and excluded roofs, wall cavities, and other inaccessible interstitial spaces. Previous survey documents of the building were reviewed. Acumen concluded that there are asbestos and lead containing materials in place at the building.

The objectives of this investigation were as follows:

- To identify regulated asbestos containing materials (RACMs), defined by Bay Area Air Quality Management District (BAAQMD). RACMs and Class I and II materials that will be rendered friable will need to be removed prior to demolition.
- To identify other asbestos containing materials that would require compliance with Cal-OSHA asbestos regulations and waste disposal regulations.
- To identify lead containing paints and ceramic tiles that would require removal prior to demolition to comply with Cal-EPA hazardous waste disposal regulations. The evaluation of paints and ceramic tiles was not intended to be either a lead inspection or a lead hazard evaluation as defined by California Department of Health Services (17CCR35001 *et seq*).

2.0 Summary of Investigation

Asbestos and Lead Containing Materials Inspection Methods

The inspection consisted of a walkthrough of accessible areas at the site to identify and sample suspect ACM and lead containing materials. Mr. Richard Rodriguez, with Facility Maintenance, escorted Acumen through the building. Acumen's standard survey protocol is to conduct asbestos inspections in three steps: conducting a review of existing building survey records and/or drawings; physically surveying structures; and documenting our findings in a written report format.

Asbestos bulk samples are physically collected by taking a small section of the suspect asbestos material using hand tools. Paints are manually collected from architectural components such as walls, and trim. Paints on mechanical components or fixtures are not typically sampled unless requested. Paints are sampled by physically collecting a paint chip and placing the sample into a clean container.

Acumen noted significant factors of suspect ACM including conditions, homogeneity, locations, quantity, potential for damage or disturbance, and friability. Friability describes the ability of a material to be crushed or crumbled, when dry, into a powder using hand pressure. Where suspect materials were noted, bulk samples were collected. At Building 23, Acumen collected thirty (30) discrete samples of suspect ACM and thirteen (13) lead samples from paint coatings and ceramic tiles.

Samples were given a unique identification number and submitted with our chain of custody forms to Micro Analytical Laboratories, Inc. (Emeryville, CA) for analysis. Micro Analytical Laboratories, Inc. is accredited to analyze asbestos air samples. Micro holds the National Institute of Standards and Technology (NIST)/ National Voluntary Laboratory Accreditation Program (NVLAP) accreditation for Transmission Electron Microscopy (TEM) (ISO/IEC 17025:1999); Polarized Light Microscopy (PLM) (EPA-600/M4-

82-020, ISO 9002:1994) Airborne Asbestos, Lab Code #101872-0 and; NIST (NVLAP), Bulk Asbestos, Lab Code 101872-0; and AIHA ELLAP Industrial Hygiene Laboratory Program, #101768.

Lead samples were analyzed by Flame Atomic Absorption (Flame AA) in accordance with EPA method 3050A. Asbestos samples were analyzed by polarized light microscopy (PLM) per U. S. Environmental Protection Agency (EPA) method 600/R-93/116, 1993. The laboratory reports are shown as Appendix A. This analytical method identifies the type(s) of asbestos present in the sample and its corresponding percent concentration(s). The reliable limit of quantification of this method is 1% asbestos by volume.

3.0 Document Review

Acumen reviewed previous documents of the building provided to us by VA PAHCS. A survey re-inspection for Building 23 entitled “Asbestos Re-evaluation for Palo Alto Veterans Hospital” was conducted by Kellco of Hayward, CA on October 1999-January 2000, and dated February 10, 2000. This reevaluation included 15 buildings at the facility including Building 23. The Kellco inspector was Gerald Martin, CAC #94-1354, and the Kellco project manager was Ms. Bonnie Kellogg. However, the report provided to us was not signed by a CAC (Ms. Kellogg) as is required by 8 CCR 1529. A copy of the report is provided in Appendix B.

The stated purpose of the re-inspection was to evaluate known ACM that was still in place and identify suspect ACM that may have not been include in the original survey. Kellco stated that they preformed a walk through, visual inspection only to update the previous survey. It was implied that “Weston” conducted the previous survey as indicated by the Kellco table title headings and their attachment content list. However, the previous report and survey date was unavailable to us as there were no attachments provided. Sampling was not part of the Kellco re-inspection service contract. Kellco stated that their scope of work was to conduct a room-by-room inspection, update the drawings, and provide a Microsoft Access database. However, Acumen noted some data gaps with Kellco’s report as there were no sample or material location drawings, room by room inspection notes, analytical reports, chains of custody, or database information showing the specific locations of previously identified and suspect ACM. Specific identifying material colors, patterns, type, sizes, and layers were generally not described. Acumen has made repeated requests to VA PAHCS for additional information but none was provided. Based upon our observations and previous data regarding asbestos content, TSI on pipes is presumed to contain asbestos.

The ACM materials listed as being still in place were presented in a table format along with materials from other buildings on site. Upon review of this table Acumen noted two columns which appear to describe the material and sample location. The column headings are “NEW designation” and “OLD designation”. It is presumed that Kellco made the “NEW” designation. The descriptions under these headings such as “23A106” is interpreted as possibly meaning that the material is from Building 23, Room 106. Acumen noted that there was no variance between the old and new designations. A copy of the re-inspection document is provided in Appendix B.

We interpreted the following materials from the tables as being Non-Asbestos Containing material(s).

- “CT 1x1” (1’ x 1’ Acoustical Ceiling Tile) (This materials was not observed by Acumen)

We interpreted the following material from the tables as being Asbestos Containing Materials

- “Pipes and elbows 23A106” (TSI on straight pipe runs and elbows) outer diameter size not listed

- *“Floor Tile 9X9 23A106A 23A106B” (9” vinyl Floor Tile) size and color not listed. This material was not observed by Acumen.*
- *“Pipes Fittings and Valves 23A10” (TSI on pipe fittings and valves - outer diameter not listed)*

4.0 Findings and Discussion

Building 23 is a one-story structure built in circa 1960. The building is constructed of concrete and brick with steel framing on a concrete slab on grade foundation. The building has approximately 18,200 square feet of total floor space. The building is designed as a recreational center with a therapeutic pool, basketball court, locker rooms and administration offices. The basketball court was recently remodeled. The building interior is finished with painted sheetrock, vinyl floor tiles, ceramic tiles, wood flooring, carpet, and 2x4’ drop in acoustical ceiling panels.

The building exterior is unpainted brick and concrete (Photos 1 and 2). Window mounted air conditioners provided have been installed at offices. Hot water is provided from the basement boiler room. This boiler room also provides hot water and steam to other facility buildings. TSI in the boiler room was found to have been replaced with fiberglass insulation. Based upon our observations the TSI in the boiler room was originally asbestos containing but has been apparently abated and replaced with fiberglass insulation. No documentation of abatement was provided to Acumen. A steam tunnel spur connects the main steam tunnel to Building 23. The spur opening is found at the boiler room. The 5” and 12” outer diameter pipes at this location are fiberglass with ACM tar paper jacketing.

TSI on pipes at the basketball court was found to be a mix of original ACM TSI and replaced fiberglass insulation. Acumen accessed the basketball court cat-walk via a wall mounted ladder to inspect TSI on pipes located along the catwalk. These pipes are associated with HVAC handling units also mounted at the cat walk level. Pipes mounted at this upper ceiling level are presumed to be ACM (PACM) (see photos 5 and 6). At first glance it appears that these pipes are only insulated with fiberglass. However, the original ACM pipe insulation (calcium silicate material) is located underneath a retrofitted jacket of fiberglass insulation.

TSI on pipes mounted horizontally, along the lower (approximately 10 foot level) north and south walls of the basketball court were found to be fiberglass only. Presumed ACM pipe insulation (calcium silicate) was also observed at the pool. This material is located at an elevated platform adjoining an HVAC unit. The insulation has suffered minor damage but no debris was observed.

Given the age of the building and the known original installation asbestos TSI, ACM pipe insulation is likely concealed within wall and ceiling cavities. It is also possible that ACM TSI is present under floors routed from the Boiler room. Destructive methods will need to be employed to assess such wall and ceiling cavities. Demolition often reveals sections of such materials that will need to be removed prior to continuing demolition activities.

Acumen collected samples of various suspect ACM at the building and determined that ACM is present as reported by the lab. Sample (SMG2801-113008-19A, 19B and 19C) exterior window putty was reported to be <1% chrysotile asbestos or Trace asbestos (Photo 1).

Sample (SMG2801-113008-20A) black tar paper wrap (jacketing) over fiberglass pipe insulation was reported 30% chrysotile asbestos. This material is located in a 25-foot long spur from the main steam tunnel, and is accessed at the Building 23 Boiler Room. The tar paper jacketing is found on both 5” and 12” outer diameter pipes (Photos 9 and 10).

Based upon our inspection of the main steam tunnel (as accessed at the building exterior grate access), supply and return lines include 5” outer diameter pipes that are insulated with presumed asbestos containing (PACM) calcium silicate and an ACM tar paper jacketing. Tar paper jacketing is found on other pipes within the main steam tunnel and is assumed to contain asbestos. All other suspect ACM materials were reported ‘None Detected’.

In addition to asbestos samples, Acumen collected representative samples for lead of paints and ceramic tile. Lead concentrations are reported in both weight percent and mg/Kg for paints and in mg/Kg for ceramic tiles. Four (4) of the six (6) ceramic tiles sampled were reported to contain lead in levels ranging from 87 up to 10,055 mg/Kg (ppm). Three (3) of the seven (7) paints sampled at Building 48 were reported to contain lead in levels ranging from 109 to 785 mg/Kg (SMG 2801-113008-01Pb, 03Pb, and 12Pb).

Based on our inspection it appears that asbestos abatement (as ACM TSI removal) has occurred at the Boiler Room and at the basketball court lower pipe runs, possibly since the Kellco report. Additional related activities appear to have included retrofitting fiberglass jacketing over the existing ACM TSI pipe runs at the upper elevations of the basketball court. No information regarding remodeling or abatement activities were made available to Acumen. Acumen recommends providing abatement documentation for review and conducting additional inspections using destructive means with supplemental bulk sampling of materials after the building is vacated.

Please refer to the Attachment A for sample chain of custody forms and analytical results. Site photographs are attached in Appendix C. Sample location drawings are included in Appendix D.

5.0 Summary of Findings

5.1 Asbestos Related Findings

The results of this investigation sampling determined that ACM materials are present at the following locations. These materials must be removed prior to demolition.

- Window Putty at building exterior
Quantity = 500 square feet
- Tar paper wrap over fiberglass pipe insulation 5” and 12” outer diameter (in steam tunnel spur to Building 23)
Quantity = 50 linear feet

The following materials are classified as Presumed Asbestos Containing Materials. These materials must be removed prior to demolition.

- Roofing materials such as built up asphalt roofs and penetration mastics
- Fire rated door core insulation
- Pipe insulation at pool, at small cat walk HVAC unit, 4’ to 6” outer diameter (minor damage)
Quantity = 10 linear feet
- Pipe insulation at basketball court cat walk elevation 4’ to 6” outer diameter
Quantity = 400 linear feet
- 5” outer diameter pipe thermal system insulation with tar paper jacketing, in main steam tunnel
- Pipe thermal system insulation in wall and ceiling cavities

5.2 *Lead Related Findings*

The results of this investigation determined that lead containing or lead based materials are present as the following. Lead containing ceramic tiles must be removed prior to demolition.

Ceramic Tiles

- 5” Gray colored Ceramic tile at cove base, Room 103 restroom
Quantity = 10 square feet
- 4” Light yellow Ceramic tile on walls up to 4 feet height, Room 103 restroom and presumed to be lead containing also at Women’ Locker Room restroom room 101
Quantity = 120 total square feet
- 4” Light green Ceramic tile on walls, up to 4 feet height, Room 102 janitor’s closet
Quantity = 90 square feet
- 6” Cream colored Ceramic tile on wall coves, swimming pool area
Quantity = 300 linear feet

Paints

- Off white paint in hallways on concrete walls
Quantity = 1,500 square feet
- Gray paint in hallways on concrete floors and coves
Quantity = 800 square feet
- White paint on exterior concrete walls
Quantity = 28,000 square feet

6.0 Other Hazardous Materials

Acumen assessed fluorescent light tubes at the building for Universal Hazardous Wastes. There are approximately 500 fluorescent tubes installed at the building. Acumen assessed representative fluorescent light tube ballasts for labeling that would indicate no PCBs are contained in the ballasts. Acumen observed that six (3) of the light ballasts inspected had labeling identifying the ballasts as not containing PCBs. Mr. Rodriguez explained to us that facilities maintenance has a policy of replacing old ballasts with new, Non-PCB ballasts when old ballasts burn out. As such, older ballasts (which may contain PCBs) and that are still working, may be in place. The abatement contractor will need to assess ballasts and segregate those without the “No PCB” labeling for proper storage and disposal.

The Department of Toxic Substances Control (DTSC) has adopted new regulations (SB 20 Electronic Waste Recycling Act) for the handling of universal waste or E-Waste. This category is a subset under all hazardous wastes. Universal wastes encompass a variety of electronic devices (including fluorescent lamps, light ballasts, mercury thermostats, cathode ray tubes, batteries, etc.) that usually contain mercury, lead, cadmium, chromium and copper. These materials are considered toxic and are banned from landfill disposal. These materials must be collected and recycled prior to demolition. Fluorescent light tubes should be carefully removed without breaking and packaged for recycling.

7.0 Recommendations

1. Acumen noted that there are fire-rated doors with suspect ACM cores. Acumen did not collect fire door core samples as this would damage fire doors and/or require the dismantling of doors. It is industry standard to inspect and collect fire door samples after the building is vacated.
2. Acumen did not collect roof samples as part of this scope of work. Roofing samples will need to be collected prior to demolition. It is recommended to wait until the building is unoccupied as we cannot guarantee that patches will not leak. Acumen can retain a professional roofing contractor who can guarantee roof patches.
3. Prior to demolition, it is recommended to use a California Department of Occupational Safety and Health (DOSH) registered asbestos contractor with CDPH certified lead trained workers to conduct the removal of lead containing ceramic tiles and asbestos containing materials.
4. It is recommended to segregate the lead containing ceramic tiles removed from other wastes. The waste stream will need to be waste characterized for lead by the California Waste Extraction Test (WET) testing methods.
5. It is recommended that removal specifications for the TSI be prepared by a certified asbestos consultant. Following abatement work it is recommended to collect asbestos clearance samples.
6. Removal costs vary based upon factors such as accessibility, material content, and waste disposal costs. It is recommended to consult with multiple abatement contractors to develop a range of accurate removal costs and options.
7. Asbestos Containing Thermal system insulation (TSI) is frequently present within wall and ceiling cavities. If additional TSI is observed during the course of demolition, these suspect materials must be presumed to be ACM until testing confirms otherwise. Contractors must be made aware that ACM TSI may be present under fiberglass insulation as observed at the basketball court. It is recommended to conduct an inspection of the building ceilings after the building is vacated and the ceiling panels can be opened for full access and view.
8. None of the lead containing paints observed were found to be deteriorated. Therefore no recommendations are made to stabilize paints (that are deteriorated) or remove lead hazards. Contractors who disturb paints at the buildings need to be informed that lead is present and/or presumed. Lead safe work practices should be implemented by the demolition contractor. Cal-OSHA's lead in construction standard (Title 8 CCR1532.1) requires a contractor to develop and implement a lead compliance plan and use lead safe construction practices. These issues are commonplace since these Cal-OSHA rules have been in effect since 1992 and since lead containing paints are commonly found at buildings constructed prior to 1978.

Please feel free to contact us if you have any questions or comments regarding this report. Thank you for the opportunity to be of service.

Limitations

Reasonable effort was made by Acumen personnel to locate and sample suspect materials. However, for any facility or building, the existence of unique or concealed ACM or lead containing materials and debris is a possibility. Acumen does not warrant, guarantee, or profess to have the ability to locate or identify all ACM/ACCM or other hazardous materials at this facility. The intent of this report is for use in planning for renovation and partial exterior and interior demolition. All quantities of materials identified in this report should be field verified by contractors prior to submitting bids to perform abatement work. Additional confirmatory sampling and detailed quantification may be required if the demolition uncovers additional suspect materials. The report is not intended as a CDPH or HUD defined “lead hazard evaluation” or “lead inspection”.

Acumen provided these services consistent with the level and skill ordinarily exercised by members of the profession currently providing similar services under similar circumstances at the time the services were provided. This statement is in lieu of other statements either expressed or implied. This report is intended for the sole use of The SmithGroup. The scope of services performed in execution of this evaluation may not be appropriate to satisfy the needs of certain other users, and use or re-use of this document, the findings, conclusions, or recommendations is at the risk of said user.

As with all such assessments, the results of the sampling represent conditions found on the date of the survey and may not represent conditions found at other times. Additionally, this assessment was limited with respect to the specific parameters indicated above and should not be construed to be a comprehensive evaluation or a definitive representation of all conditions within the facility. The information presented in this report is intended to be used as a guide to evaluate the need for materials removal, further investigation or the need for modifications to the processes or procedures surveyed.

The client should recognize that all testing and remediation methods have reliability limitations, no method or number of sampling locations can guarantee that a condition will be discovered within the performance of the services as authorized by the client. Additionally, the passage of time may result in a change in the environmental characteristics at this site. This report does not warrant against future operations or conditions that could affect the recommendations made. The results, findings, conclusions, and recommendations expressed in this report are based only on conditions that were observed during Acumens’ inspection of the site.

Table 1

Asbestos Containing Materials
VA Hospital
Building 23
Palo Alto, CA

November 3, 2008

| Location | Material | Results ¹ | BAAQMD ² | EQ ³ | Sample No. |
|--------------------------------------|---|------------------------|---------------------|---------------------------------|-------------------|
| Building exterior | Window putty | <1% CH | Cat II - NF | 500 total sf | SMG2801-11308-19A |
| Steam Tunnel accessed in Boiler Room | Black tar paper wrap over F/G insulated pipes in steam tunnel | Tar paper wrap: 30% CH | Cat II - NF | 5" OD = 25 lf 12" OD = 25 lf | SMG2801-11308-20A |
| Roof | Built up asphalt roofing and penetration mastics | Assumed | Cat I - NF | 18,500 sf | N/A |
| Utility Room Doors | Fire rated door core insulation | Assumed | RACM | Not quantified | N/A |
| Gym and Pool | Pipe insulation | Assumed | RACM | 410 linear feet | N/A |
| Wall/Ceiling Cavities | Pipe insulation | Assumed | RACM | Not quantified | N/A |
| Steam Tunnel | 5" outer diameter pipe thermal system insulation with tar paper jacketing | Assumed | RACM | Not quantified | N/A |

Footnotes

1. Results report percent (%) asbestos as determined by polarized light microscopy (PLM). CH indicates Chrysotile asbestos and ND indicates that asbestos was not detected.
2. BAAQMD indicates classification into friable (RACM) or non-friable (Cat I or Cat II) ACM.
3. EQ means estimated quantity either in square feet (sf) or linear feet (lf).
4. OD means the outer diameter of a pipe

Table 2

Non-Asbestos Containing Materials
VA Hospital
Building 23
Palo Alto, CA

November 3, 2008

| Location | Material | Results ¹ | Sample No. |
|---|--|---|-------------------|
| Basketball court deck west (at catwalk level) | HVAC duct woven canvas wrap over fiberglass | Canvas wrap: ND Fiberglass insulation: ND Paint: ND Glue: ND | SMG2801-11308-01A |
| Basketball court deck east (at catwalk level) | HVAC duct woven canvas wrap over fiberglass | Canvas wrap: ND Fiberglass insulation: ND Paint: ND Glue: ND | SMG2801-11308-01B |
| Basketball court deck west (at catwalk level) | HVAC duct woven canvas wrap over fiberglass | Canvas wrap: ND Fiberglass insulation: ND Paint: ND Glue: ND | SMG2801-11308-01C |
| Basketball court | 4" yellow cove mastic | Yellow mastic: ND Compound: ND | SMG2801-11308-02A |
| 106A storage room wall | Plaster layers | Plaster: ND Skim coat: ND Paint: ND | SMG2801-11308-03A |
| Hallway fire closet wall | Plaster layers | Plaster: ND Skim coat: ND Paint: ND | SMG2801-11308-03B |
| Hallway wall | Plaster layers | Plaster: ND Skim coat: ND Paint: ND | SMG2801-11308-03C |
| 106A | 12" white with black specks vinyl floor tile and yellow mastic | Vinyl floor tile: ND Yellow mastic: ND | SMG2801-11308-04A |

Footnote

1. All samples analyzed by polarized light microscopy and reported as not containing detectable amounts of asbestos. ND indicates that asbestos was not detected.

Table 2 (continued)

Non-Asbestos Containing Materials
VA Hospital
Building 23
Palo Alto, CA

November 3, 2008

| Location | Material | Results ¹ | Sample No. |
|---------------------------|--|---|-------------------|
| 106A | Gray floor tile with brown mastic under 12" white with black specks vinyl floor tile and yellow mastic | Floor tile: ND Brown mastic: ND | SMG2801-11308-05A |
| 105 | 12" yellow mottled vinyl floor tile and amber mastic | Vinyl floor tile: ND Amber mastic: ND | SMG2801-11308-06A |
| 109 | 2x4' drop-in acoustical ceiling panels with small random holes | ND | SMG2801-11308-07A |
| 109 | 2x4' drop-in acoustical ceiling panels with small random holes | ND | SMG2801-11308-07B |
| 109 | 2x4' drop-in acoustical ceiling panels with small random holes | Ceiling tile: ND White coating: ND | SMG2801-11308-07C |
| Restroom 103 | Mortar on 5" ceramic tile gray cove | Ceramic tile: ND Mortar: ND | SMG2801-11308-08A |
| Restroom 103 | Grout on 5" ceramic tile gray cove | ND | SMG2801-11308-09A |
| 103 | Grout on 5" ceramic tile on walls | ND | SMG2801-11308-10A |
| 103 | Mortar on 4" ceramic tile on walls | Light gray mortar: ND Dark gray mortar: ND | SMG2801-11308-11A |
| Janitor's closet room 102 | Grout on 4" ceramic tile | ND | SMG2801-11308-12A |
| Janitor's closet room 102 | Mortar on 4" ceramic tile | White mortar: ND Gray mortar: ND | SMG2801-11308-13A |
| Steps at swimming pool | Grout on 1" beige ceramic tile | ND | SMG2801-11308-14A |

Footnote

1. All samples analyzed by polarized light microscopy and reported as not containing detectable amounts of asbestos. ND indicates that asbestos was not detected.

Table 2 (continued)

Non-Asbestos Containing Materials
VA Hospital
Building 23
Palo Alto, CA

November 3, 2008

| Location | Material | Results ¹ | Sample No. |
|--------------------------------|---|---|-------------------|
| Steps at swimming pool | Mortar on 1" beige ceramic tile | Ceramic tile: ND Dark gray mortar: ND Light gray mortar: ND | SMG2801-11308-15A |
| Swimming pool southwest corner | Sheetrock composite | Sheetrock: ND Joint compound: ND Paint: ND | SMG2801-11308-16A |
| Swimming pool northeast | Sheetrock composite | Sheetrock: ND Joint compound: ND Paint: ND | SMG2801-11308-16B |
| Swimming pool west center | Sheetrock composite | Sheetrock: ND Joint compound: ND Paint: ND | SMG2801-11308-16C |
| Swimming pool southwest | Grout on 6" cream ceramic tile on cove base | Grout: ND | SMG2801-11308-17A |
| - | Mastic | Mastic: ND | SMG2801-11308-18A |

Footnote

1. All samples analyzed by polarized light microscopy and reported as not containing detectable amounts of asbestos. ND indicates that asbestos was not detected.

Table 3

Summary of Ceramic Tile Lead Results
VA Hospital
Building 23
Palo Alto, CA

November 3, 2008

| Location | Material | Result ¹ | Sample No. |
|----------------------------|---------------------------------------|---------------------|--------------------|
| Locker 100 | 6x11' light yellow ceramic wall tiles | <9.7 | SMG2801-11308-04PB |
| Restroom | 5" gray ceramic tile at cove | 10,055 | SMG2801-11308-06PB |
| Restroom 103 wall up to 4' | 4" ceramic tile | 9,212.4 | SMG2801-11308-07PB |
| Janitor's closet 102 | 4" ceramic wall tile | 8,292.5 | SMG2801-11308-08PB |
| Swimming pool steps | 1' beige ceramic floor tile | <9.7 | SMG2801-11308-09PB |
| Swimming pool southwest | 6" ceramic tile cream on coves | 87 | SMG2801-11308-10PB |

Footnote

1. Results were analyzed by Flame Atomic Absorption Spectrometry EPA Methods 3054A and 7420 and are shown in milligrams per kilograms (mg/Kg) or parts per million (ppm).

Table 4

Summary of Lead Paint Results
VA Hospital
Building 23
Palo Alto, CA

November 3, 2008

| Location | Material | Result ¹ | Sample No. |
|----------------------------|--|---------------------|--------------------|
| Hall at restroom 103 | Off-white paint concrete wall | 619 | SMG2801-11308-01PB |
| Basketball court west | Off-white paint on concrete column and walls | <60 | SMG2801-11308-02PB |
| Hallways | Gray paint on concrete floors and cove | 785 | SMG2801-11308-03PB |
| Room 110 lower | Cream paint on floors and cove | <73 | SMG2801-11308-05PB |
| Swimming pool at southwest | Institutional green paint on sheetrock wall | <76 | SMG2801-11308-11PB |
| Exterior | Off-white paint on concrete | 109 | SMG2801-11308-12PB |
| Locker room | Off-white paint on walls | <74 | SMG2801-11308-13PB |

Footnote

1. Results were analyzed by Flame Atomic Absorption Spectrometry EPA Method 7420 and are shown in milligrams per kilograms (mg/kg) or parts per million (ppm). Please refer to the lab reports for weight percent as needed.

Appendix A

Laboratory Reports

Palo Alto Veterans Administration Hospital
Building 23
Palo Alto, CA

November 3, 2008

Acumen Project No SMG 2801B

Prepared For:

SmithGroup/The Design Partnership Associate
301 Battery Street, 7th floor
San Francisco, CA

MICRO ANALYTICAL LABORATORIES, INC.

Page 1 of 6

BULK ASBESTOS ANALYSIS - PLM (EPA/600/R-93/116, 1993)

1092
Paul Spillane
Acumen Industrial Hygiene, Inc.
1032 Irving Street, #922
San Francisco, CA 94122-2216

PROJECT:
**VA PALO ALTO
BUILDING 23
PROJECT NO. SMG2801**

Micro Log In **118017**
Total Samples 30
Date Sampled 11/03/2008
Date Received 11/04/2008
Date Analyzed 11/04/2008

ASBESTOS INFORMATION

SAMPLE IDENTIFICATION

QUANTITY (AREA %) / TYPES / LAYERS / DISTINCT SAMPLES

DOMINANT OTHER MATERIALS

| | | |
|--|---|--|
| Client: SMG2801-11308-01A Micro: 118017-01 Analyst: DA HVAC DUCT WOVEN CANVAS WRAP OVER FIBERGLASS BASKETBALL COURT DECK - WEST | CANVAS WRAP: NONE DETECTED FIBERGLASS INSULATION: NONE DETECTED PAINT: NONE DETECTED GLUE: NONE DETECTED | 20 % CELLULOSE 20 % FIBROUS GLASS Matrix Type: SYNTHETIC MATERIAL |
| Client: SMG2801-11308-01B Micro: 118017-02 Analyst: DA HVAC DUCT WOVEN CANVAS WRAP OVER FIBERGLASS BASKETBALL COURT DECK - EAST | CANVAS WRAP: NONE DETECTED FIBERGLASS INSULATION: NONE DETECTED PAINT: NONE DETECTED GLUE: NONE DETECTED | 20 % CELLULOSE 20 % FIBROUS GLASS Matrix Type: SYNTHETIC MATERIAL |
| Client: SMG2801-11308-01C Micro: 118017-03 Analyst: DA HVAC DUCT WOVEN CANVAS WRAP OVER FIBERGLASS BASKETBALL COURT DECK - WEST | CANVAS WRAP: NONE DETECTED FIBERGLASS INSULATION: NONE DETECTED PAINT: NONE DETECTED GLUE: NONE DETECTED | 20 % CELLULOSE 20 % FIBROUS GLASS Matrix Type: SYNTHETIC MATERIAL |
| Client: SMG2801-11308-02A Micro: 118017-04 Analyst: DA 4" COVE MASTIC - YELLOW BASKETBALL COURT | MASTIC (YELLOW): NONE DETECTED COMPOUND: NONE DETECTED | Matrix: CARBONATE Type: SYNTHETIC MATERIAL |
| Client: SMG2801-11308-03A Micro: 118017-05 Analyst: DA PLASTER LAYERS 106A STG. ROOM | PLASTER: NONE DETECTED SKIM COAT: NONE DETECTED PAINT: NONE DETECTED | 2 % CELLULOSE Matrix: GYPSUM Type: ROCK FRAGMENTS |

Technical Supervisor:


FOR: Gamini Ranatunga, Ph.D.

11/6/2008

Date Reported

Asbestos is quantified by calibrated visual estimation. Detection limit is material dependent. Detection of asbestos traces (much less than 1%) may not be reliable or reproducible by PLM. Weight % cannot be determined by PLM. Asbestos with diameter below ~1 µm may not be detected by PLM. Absence of asbestos in dust, debris, and some compact materials, including floor tiles, cannot be conclusively established by PLM, and should be confirmed by Transmission Electron Microscopy (TEM). The lower quantitation limit (reporting limit) of PLM estimation is 1%. The Cal-OSHA definition of asbestos-containing construction material is 0.1% asbestos; however, reliable determination of asbestos percent at this level cannot be done by PLM estimation; PLM Point Counting or TEM is recommended. Only dominant non-asbestos materials are indicated. Interferences may prevent detection of small asbestos fibers, and hinder determination of some optical properties. Sample heterogeneity is indicated by listing more than one distinct layer or material on the report. Layers are analyzed separately when feasible; if asbestos is detected, percentages are reported for individual layers. Interlayer contamination is possible among any layers in a sample. Composite asbestos percentages are applicable only to wallboard / joint compound systems; compositing is based on customers' descriptions of material as "joint compound". Customers are solely responsible for identification and description of bulk materials listed on field forms. Laboratory descriptions may differ from those given by customers. Quality Control (QC) Codes: A1/A2 = results within acceptance limits; F = false positive or negative corrected, reanalysis within acceptance limits; M = Method error resolved (for trace amounts); R = Other, resolved after review. Accreditation: NIST / NVLAP (Lab Code 101872-0). CA ELAP Certification #1037. EPA 1993 method is based on EPA Interim Method (1982), with improved analytical techniques. Unless otherwise stated herein, all samples were received in acceptable condition for analysis. This report must not be used to claim product endorsement by NIST or any U.S. Government agency. This report shall not be reproduced without the approval of Micro Analytical Laboratories, Inc., shall not be reproduced except in full, and pertains only to the samples analyzed. ND = NO ASBESTOS DETECTED.

5900 HOLLIS STREET, SUITE M - EMERYVILLE, CA 94608 - (510) 653-0824

MICRO ANALYTICAL LABORATORIES, INC.

Page 2 of 6

BULK ASBESTOS ANALYSIS - PLM (EPA/600/R-93/116, 1993)

1092
Paul Spillane
Acumen Industrial Hygiene, Inc.
1032 Irving Street, #922
San Francisco, CA 94122-2216

PROJECT:
**VA PALO ALTO
BUILDING 23
PROJECT NO. SMG2801**

Micro Log In **118017**
Total Samples 30
Date Sampled 11/03/2008
Date Received 11/04/2008
Date Analyzed 11/04/2008

ASBESTOS INFORMATION

SAMPLE IDENTIFICATION

QUANTITY (AREA %) / TYPES / LAYERS / DISTINCT SAMPLES

DOMINANT OTHER MATERIALS

| | | |
|---|---|---|
| Client: SMG2801-11308-03B Micro: 118017-06 Analyst: DA GR PLASTER LAYERS HALLWAY - FIRE CLOSET | PLASTER: NONE DETECTED SKIM COAT: NONE DETECTED PAINT: NONE DETECTED | 2 % CELLULOSE Matrix: GYPSUM Type: ROCK FRAGMENTS QC: A2 |
| Client: SMG2801-11308-03C Micro: 118017-07 Analyst: DA PLASTER LAYERS - HALLWAY | PLASTER: NONE DETECTED SKIM COAT: NONE DETECTED PAINT: NONE DETECTED | 2 % CELLULOSE Matrix: GYPSUM Type: ROCK FRAGMENTS |
| Client: SMG2801-11308-04A Micro: 118017-08 Analyst: DA 12" VFT WHITE WITH BLACK SPECKS AND YELLOW MASTIC - 106A | VFT: NONE DETECTED MASTIC (YELLOW): NONE DETECTED | Matrix: CARBONATE Type: SYNTHETIC MATERIAL |
| Client: SMG2801-11308-05A Micro: 118017-09 Analyst: DA GRAY FLOOR TILES WITH BROWN MASTIC (UNDERNEATH 04A) - 106A | FLOOR TILE: NONE DETECTED MASTIC (BROWN): NONE DETECTED | 4 % CELLULOSE 1 % FIBROUS GLASS Matrix: CARBONATE Type: SYNTHETIC MATERIAL |
| Client: SMG2801-11308-06A Micro: 118017-10 Analyst: DA 12" VFT - YELLOW MOTTLED AMBER MASTIC - 105 | VFT: NONE DETECTED MASTIC (AMBER): NONE DETECTED | Matrix: CARBONATE Type: SYNTHETIC MATERIAL |

Technical Supervisor:


FOR: Gamini Ranatunga, Ph.D.

11/6/2008

Date Reported

Asbestos is quantified by calibrated visual estimation. Detection limit is material dependent. Detection of asbestos traces (much less than 1%) may not be reliable or reproducible by PLM. Weight % cannot be determined by PLM. Asbestos with diameter below ~1 µm may not be detected by PLM. Absence of asbestos in dust, debris, and some compact materials, including floor tiles, cannot be conclusively established by PLM, and should be confirmed by Transmission Electron Microscopy (TEM). The lower quantitation limit (reporting limit) of PLM estimation is 1%. The Cal-OSHA definition of asbestos-containing construction material is 0.1% asbestos; however, reliable determination of asbestos percent at this level cannot be done by PLM estimation; PLM Point Counting or TEM is recommended. Only dominant non-asbestos materials are indicated. Interferences may prevent detection of small asbestos fibers, and hinder determination of some optical properties. Sample heterogeneity is indicated by listing more than one distinct layer or material on the report. Layers are analyzed separately when feasible; if asbestos is detected, percentages are reported for individual layers. Interlayer contamination is possible among any layers in a sample. Composite asbestos percentages are applicable only to wallboard / joint compound systems; compositing is based on customers' descriptions of material as "joint compound". Customers are solely responsible for identification and description of bulk materials listed on field forms. Laboratory descriptions may differ from those given by customers. Quality Control (QC) Codes: A1/A2 = results within acceptance limits; F = false positive or negative corrected, reanalysis within acceptance limits; M = Method error resolved (for trace amounts); R = Other, resolved after review. Accreditation: NIST / NVLAP (Lab Code 101872-0). CA ELAP Certification #1037. EPA 1993 method is based on EPA Interim Method (1982), with improved analytical techniques. Unless otherwise stated herein, all samples were received in acceptable condition for analysis. This report must not be used to claim product endorsement by NIST or any U.S. Government agency. This report shall not be reproduced without the approval of Micro Analytical Laboratories, Inc., shall not be reproduced except in full, and pertains only to the samples analyzed. ND = NO ASBESTOS DETECTED.

5900 HOLLIS STREET, SUITE M - EMERYVILLE, CA 94608 - (510) 653-0824

MICRO ANALYTICAL LABORATORIES, INC.

Page 3 of 6

BULK ASBESTOS ANALYSIS - PLM (EPA/600/R-93/116, 1993)

1092
Paul Spillane
Acumen Industrial Hygiene, Inc.
1032 Irving Street, #922
San Francisco, CA 94122-2216

PROJECT:
**VA PALO ALTO
BUILDING 23
PROJECT NO. SMG2801**

Micro Log In **118017**
Total Samples 30
Date Sampled 11/03/2008
Date Received 11/04/2008
Date Analyzed 11/04/2008

ASBESTOS INFORMATION


SAMPLE IDENTIFICATION

QUANTITY (AREA %) / TYPES / LAYERS / DISTINCT SAMPLES

DOMINANT OTHER MATERIALS

| | | |
|--|---|---|
| Client: SMG2801-11308-07A Micro: 118017-11 Analyst: DA 2' X 4' DROP IN ACOUSTICAL CEILING PANELS WITH SMALL RANDOM HOLES - 109 | NONE DETECTED | 60 % FIBROUS GLASS Matrix: BINDER Type: GLASS FRAGMENTS |
| Client: SMG2801-11308-07B Micro: 118017-12 Analyst: DA 2' X 4' DROP IN ACOUSTICAL CEILING PANELS WITH SMALL RANDOM HOLES - 109 | NONE DETECTED | 60 % FIBROUS GLASS Matrix: BINDER Type: GLASS FRAGMENTS |
| Client: SMG2801-11308-07C Micro: 118017-13 Analyst: DA 2' X 4' DROP IN ACOUSTICAL CEILING PANELS WITH SMALL RANDOM HOLES - 109 | CEILING TILE: NONE DETECTED COATING (WHITE): NONE DETECTED | 60 % FIBROUS GLASS Matrix: GLASS FRAGMENTS Type: SYNTHETIC MATERIAL |
| Client: SMG2801-11308-08A Micro: 118017-14 Analyst: DA MORTAR ON 5" CERAMIC TILE GRAY COVE - RESTROOM 103 | CERAMIC TILE: NONE DETECTED MORTAR: NONE DETECTED | Matrix: CARBONATE Type: ROCK FRAGMENTS |
| Client: SMG2801-11308-09A Micro: 118017-15 Analyst: DA GROUT ON ABOVE - RESTROOM 103 | NONE DETECTED | 2 % CELLULOSE Matrix: CARBONATE Type: SYNTHETIC MATERIAL |

Technical Supervisor:


FOR: Gamini Ranatunga, Ph.D.

11/6/2008

Date Reported

Asbestos is quantified by calibrated visual estimation. Detection limit is material dependent. Detection of asbestos traces (much less than 1%) may not be reliable or reproducible by PLM. Weight % cannot be determined by PLM. Asbestos with diameter below ~1 µm may not be detected by PLM. Absence of asbestos in dust, debris, and some compact materials, including floor tiles, cannot be conclusively established by PLM, and should be confirmed by Transmission Electron Microscopy (TEM). The lower quantitation limit (reporting limit) of PLM estimation is 1%. The Cal-OSHA definition of asbestos-containing construction material is 0.1% asbestos; however, reliable determination of asbestos percent at this level cannot be done by PLM estimation; PLM Point Counting or TEM is recommended. Only dominant non-asbestos materials are indicated. Interferences may prevent detection of small asbestos fibers, and hinder determination of some optical properties. Sample heterogeneity is indicated by listing more than one distinct layer or material on the report. Layers are analyzed separately when feasible; if asbestos is detected, percentages are reported for individual layers. Interlayer contamination is possible among any layers in a sample. Composite asbestos percentages are applicable only to wallboard / joint compound systems; compositing is based on customers' descriptions of material as "joint compound". Customers are solely responsible for identification and description of bulk materials listed on field forms. Laboratory descriptions may differ from those given by customers. Quality Control (QC) Codes: A1/A2 = results within acceptance limits; F = false positive or negative corrected, reanalysis within acceptance limits; M = Method error resolved (for trace amounts); R = Other, resolved after review. Accreditation: NIST / NVLAP (Lab Code 101872-0). CA ELAP Certification #1037. EPA 1993 method is based on EPA Interim Method (1982), with improved analytical techniques. Unless otherwise stated herein, all samples were received in acceptable condition for analysis. This report must not be used to claim product endorsement by NIST or any U.S. Government agency. This report shall not be reproduced without the approval of Micro Analytical Laboratories, Inc., shall not be reproduced except in full, and pertains only to the samples analyzed. ND = NO ASBESTOS DETECTED.

5900 HOLLIS STREET, SUITE M - EMERYVILLE, CA 94608 - (510) 653-0824

MICRO ANALYTICAL LABORATORIES, INC.

Page 4 of 6

BULK ASBESTOS ANALYSIS - PLM (EPA/600/R-93/116, 1993)

1092
Paul Spillane
Acumen Industrial Hygiene, Inc.
1032 Irving Street, #922
San Francisco, CA 94122-2216

PROJECT:
**VA PALO ALTO
BUILDING 23
PROJECT NO. SMG2801**

Micro Log In **118017**
Total Samples 30
Date Sampled 11/03/2008
Date Received 11/04/2008
Date Analyzed 11/04/2008

ASBESTOS INFORMATION

SAMPLE IDENTIFICATION

QUANTITY (AREA %) / TYPES / LAYERS / DISTINCT SAMPLES

DOMINANT OTHER MATERIALS

| | | |
|--|---|--|
| Client: SMG2801-11308-10A Micro: 118017-16 Analyst: DA GROUT ON 4" CERAMIC TILE ON WALLS 103 | NONE DETECTED | Matrix: Type: CARBONATE |
| Client: SMG2801-11308-11A Micro: 118017-17 Analyst: DA GR MORTAR ON 4" CERAMIC TILE ON WALLS - 103 | MORTAR (LIGHT GRAY): NONE DETECTED MORTAR (DARK GRAY): NONE DETECTED | 1 % CELLULOSE Matrix: CARBONATE Type: ROCK FRAGMENTS QC: A2 |
| Client: SMG2801-11308-12A Micro: 118017-18 Analyst: DA GROUT ON 4" CERAMIC TILE JANITOR'S CLOSET - ROOM 102 | NONE DETECTED | Matrix: CARBONATE Type: SYNTHETIC MATERIAL |
| Client: SMG2801-11308-13A Micro: 118017-19 Analyst: DA MORTAR ON 4" CERAMIC TILE JANITORS CLOSET - ROOM 102 | MORTAR (WHITE): NONE DETECTED MORTAR (GRAY): NONE DETECTED | Matrix: CARBONATE Type: ROCK FRAGMENTS |
| Client: SMG2801-11308-14A Micro: 118017-20 Analyst: DA GROUT ON 1" BEIGE CERAMIC TILE STEPS AT SWIMMING POOL | NONE DETECTED | Matrix: CARBONATE Type: ROCK FRAGMENTS |

Technical Supervisor:


for Gamini Ranatunga, Ph.D.

11/6/2008

Date Reported

Asbestos is quantified by calibrated visual estimation. Detection limit is material dependent. Detection of asbestos traces (much less than 1%) may not be reliable or reproducible by PLM. Weight % cannot be determined by PLM. Asbestos with diameter below ~1 µm may not be detected by PLM. Absence of asbestos in dust, debris, and some compact materials, including floor tiles, cannot be conclusively established by PLM, and should be confirmed by Transmission Electron Microscopy (TEM). The lower quantitation limit (reporting limit) of PLM estimation is 1%. The Cal-OSHA definition of asbestos-containing construction material is 0.1% asbestos; however, reliable determination of asbestos percent at this level cannot be done by PLM estimation; PLM Point Counting or TEM is recommended. Only dominant non-asbestos materials are indicated. Interferences may prevent detection of small asbestos fibers, and hinder determination of some optical properties. Sample heterogeneity is indicated by listing more than one distinct layer or material on the report. Layers are analyzed separately when feasible; if asbestos is detected, percentages are reported for individual layers. Interlayer contamination is possible among any layers in a sample. Composite asbestos percentages are applicable only to wallboard / joint compound systems; compositing is based on customers' descriptions of material as "joint compound". Customers are solely responsible for identification and description of bulk materials listed on field forms. Laboratory descriptions may differ from those given by customers. Quality Control (QC) Codes: A1/A2 = results within acceptance limits; F = false positive or negative corrected, reanalysis within acceptance limits; M = Method error resolved (for trace amounts); R = Other, resolved after review. Accreditation: NIST / NVLAP (Lab Code 101872-0). CA ELAP Certification #1037. EPA 1993 method is based on EPA Interim Method (1982), with improved analytical techniques. Unless otherwise stated herein, all samples were received in acceptable condition for analysis. This report must not be used to claim product endorsement by NIST or any U.S. Government agency. This report shall not be reproduced without the approval of Micro Analytical Laboratories, Inc., shall not be reproduced except in full, and pertains only to the samples analyzed. ND = NO ASBESTOS DETECTED.

5900 HOLLIS STREET, SUITE M - EMERYVILLE, CA 94608 - (510) 653-0824

MICRO ANALYTICAL LABORATORIES, INC.

Page 5 of 6

BULK ASBESTOS ANALYSIS - PLM (EPA/600/R-93/116, 1993)

1092
Paul Spillane
Acumen Industrial Hygiene, Inc.
1032 Irving Street, #922
San Francisco, CA 94122-2216

PROJECT:
**VA PALO ALTO
BUILDING 23
PROJECT NO. SMG2801**

Micro Log In **118017**
Total Samples 30
Date Sampled 11/03/2008
Date Received 11/04/2008
Date Analyzed 11/05/2008

ASBESTOS INFORMATION


SAMPLE IDENTIFICATION

QUANTITY (AREA %) / TYPES / LAYERS / DISTINCT SAMPLES

DOMINANT OTHER MATERIALS

| | | |
|---|---|--|
| Client: SMG2801-11308-15A Micro: 118017-21 Analyst: DA MORTAR ON 1" BEIGE CERAMIC TILE STEPS AT SWIMMING POOL | CERAMIC TILE: NONE DETECTED MORTAR (DARK GRAY): NONE DETECTED MORTAR (LIGHT GRAY): NONE DETECTED | Matrix: Type: ROCK FRAGMENTS |
| Client: SMG2801-11308-16A Micro: 118017-22 Analyst: DA SHEETROCK COMPOSITE SWIMMING POOL SOUTHWEST CORNER | SHEETROCK: NONE DETECTED JOINT COMPOUND: NONE DETECTED PAINT: NONE DETECTED | 10 % CELLULOSE 2 % FIBROUS GLASS Matrix: MIXED CARBONATE - Type: GYPSUM |
| Client: SMG2801-11308-16B Micro: 118017-23 Analyst: DA SHEETROCK COMPOSITE SWIMMING POOL NORTHEAST | SHEETROCK: NONE DETECTED JOINT COMPOUND: NONE DETECTED PAINT: NONE DETECTED | 10 % CELLULOSE 2 % FIBROUS GLASS Matrix: MIXED CARBONATE - Type: GYPSUM |
| Client: SMG2801-11308-16C Micro: 118017-24 Analyst: DA GR SHEETROCK COMPOSITE SWIMMING POOL WEST CENTER | SHEETROCK: NONE DETECTED JOINT COMPOUND: NONE DETECTED PAINT: NONE DETECTED | 10 % CELLULOSE 2 % FIBROUS GLASS Matrix: MIXED CARBONATE - Type: GYPSUM QC: A2 |
| Client: SMG2801-11308-17A Micro: 118017-25 Analyst: DA GROUT ON 6" CERAMIC TILE CREAM ON COVE SWIMMING POOL - SOUTHWEST | GROUT: NONE DETECTED | Matrix: CARBONATE Type: SYNTHETIC MATERIAL |

Technical Supervisor:


Gamini Ranatunga, Ph.D.

11/6/2008

Date Reported

Asbestos is quantified by calibrated visual estimation. Detection limit is material dependent. Detection of asbestos traces (much less than 1%) may not be reliable or reproducible by PLM. Weight % cannot be determined by PLM. Asbestos with diameter below ~1 µm may not be detected by PLM. Absence of asbestos in dust, debris, and some compact materials, including floor tiles, cannot be conclusively established by PLM, and should be confirmed by Transmission Electron Microscopy (TEM). The lower quantitation limit (reporting limit) of PLM estimation is 1%. The Cal-OSHA definition of asbestos-containing construction material is 0.1% asbestos; however, reliable determination of asbestos percent at this level cannot be done by PLM estimation; PLM Point Counting or TEM is recommended. Only dominant non-asbestos materials are indicated. Interferences may prevent detection of small asbestos fibers, and hinder determination of some optical properties. Sample heterogeneity is indicated by listing more than one distinct layer or material on the report. Layers are analyzed separately when feasible; if asbestos is detected, percentages are reported for individual layers. Interlayer contamination is possible among any layers in a sample. Composite asbestos percentages are applicable only to wallboard / joint compound systems; compositing is based on customers' descriptions of material as "joint compound". Customers are solely responsible for identification and description of bulk materials listed on field forms. Laboratory descriptions may differ from those given by customers. Quality Control (QC) Codes: A1/A2 = results within acceptance limits; F = false positive or negative corrected, reanalysis within acceptance limits; M = Method error resolved (for trace amounts); R = Other, resolved after review. Accreditation: NIST / NVLAP (Lab Code 101872-0). CA ELAP Certification #1037. EPA 1993 method is based on EPA Interim Method (1982), with improved analytical techniques. Unless otherwise stated herein, all samples were received in acceptable condition for analysis. This report must not be used to claim product endorsement by NIST or any U.S. Government agency. This report shall not be reproduced without the approval of Micro Analytical Laboratories, Inc., shall not be reproduced except in full, and pertains only to the samples analyzed. ND = NO ASBESTOS DETECTED.

5900 HOLLIS STREET, SUITE M - EMERYVILLE, CA 94608 - (510) 653-0824

MICRO ANALYTICAL LABORATORIES, INC.

Page 6 of 6

BULK ASBESTOS ANALYSIS - PLM (EPA/600/R-93/116, 1993)

1092
Paul Spillane
Acumen Industrial Hygiene, Inc.
1032 Irving Street, #922
San Francisco, CA 94122-2216

PROJECT:
**VA PALO ALTO
BUILDING 23
PROJECT NO. SMG2801**

Micro Log In **118017**
Total Samples 30
Date Sampled 11/03/2008
Date Received 11/04/2008
Date Analyzed 11/05/2008

ASBESTOS INFORMATION


SAMPLE IDENTIFICATION

QUANTITY (AREA %) / TYPES / LAYERS / DISTINCT SAMPLES

DOMINANT OTHER MATERIALS

| | | |
|---|--|--|
| Client: SMG2801-11308-18A Micro: 118017-26 Analyst: DA MASTIC | MASTIC: NONE DETECTED | Matrix: CARBONATE Type: SYNTHETIC MATERIAL |
| Client: SMG2801-11308-19A Micro: 118017-27 Analyst: DA WINDOW PUTTY BUILDING EXTERIOR SOUTHWEST | < 1% CHRYSOTILE ASBESTOS | Matrix: CARBONATE Type: SYNTHETIC MATERIAL |
| Client: SMG2801-11308-19B Micro: 118017-28 Analyst: DA WINDOW PUTTY BUILDING EXTERIOR WEST CENTER | < 1% CHRYSOTILE ASBESTOS | Matrix: CARBONATE Type: SYNTHETIC MATERIAL |
| Client: SMG2801-11308-19C Micro: 118017-29 Analyst: DA GR WINDOW PUTTY BUILDING EXTERIOR NORTHWEST | < 1% CHRYSOTILE ASBESTOS | Matrix: CARBONATE Type: SYNTHETIC MATERIAL QC: A1 |
| Client: SMG2801-11308-20A Micro: 118017-30 Analyst: DA BLACK TAR PAPER WRAP OVER F/G INSULATED PIPES IN STEAM TUNNEL - 23 | TAR PAPER WRAP: 30% CHRYSOTILE ASBESTOS | 3 % CELLULOSE 1 % FIBROUS GLASS Matrix: TAR Type: TAR |

Technical Supervisor:


FMA: Gamini Ranatunga, Ph.D.

11/6/2008

Date Reported

Asbestos is quantified by calibrated visual estimation. Detection limit is material dependent. Detection of asbestos traces (much less than 1%) may not be reliable or reproducible by PLM. Weight % cannot be determined by PLM. Asbestos with diameter below ~1 µm may not be detected by PLM. Absence of asbestos in dust, debris, and some compact materials, including floor tiles, cannot be conclusively established by PLM, and should be confirmed by Transmission Electron Microscopy (TEM). The lower quantitation limit (reporting limit) of PLM estimation is 1%. The Cal-OSHA definition of asbestos-containing construction material is 0.1% asbestos; however, reliable determination of asbestos percent at this level cannot be done by PLM estimation; PLM Point Counting or TEM is recommended. Only dominant non-asbestos materials are indicated. Interferences may prevent detection of small asbestos fibers, and hinder determination of some optical properties. Sample heterogeneity is indicated by listing more than one distinct layer or material on the report. Layers are analyzed separately when feasible; if asbestos is detected, percentages are reported for individual layers. Interlayer contamination is possible among any layers in a sample. Composite asbestos percentages are applicable only to wallboard / joint compound systems; compositing is based on customers' descriptions of material as "joint compound". Customers are solely responsible for identification and description of bulk materials listed on field forms. Laboratory descriptions may differ from those given by customers. Quality Control (QC) Codes: A1/A2 = results within acceptance limits; F = false positive or negative corrected, reanalysis within acceptance limits; M = Method error resolved (for trace amounts); R = Other, resolved after review. Accreditation: NIST / NVLAP (Lab Code 101872-0). CA ELAP Certification #1037. EPA 1993 method is based on EPA Interim Method (1982), with improved analytical techniques. Unless otherwise stated herein, all samples were received in acceptable condition for analysis. This report must not be used to claim product endorsement by NIST or any U.S. Government agency. This report shall not be reproduced without the approval of Micro Analytical Laboratories, Inc., shall not be reproduced except in full, and pertains only to the samples analyzed. ND = NO ASBESTOS DETECTED.

5900 HOLLIS STREET, SUITE M - EMERYVILLE, CA 94608 - (510) 653-0824



ACUMEN

INDUSTRIAL HYGIENE INC

1032 IRVING ST. - BOX 922 SAN FRANCISCO CA 94122

TEL 415 242 6060 FAX 415 242 6006

WWW.ACUMEN-IH.COM

BULK CHAIN OF CUSTODY FORM

118017

Project No. SMG 2801

Job Site: VA PALO ALTO

Laboratory:

Location: BUILDING 23

Turnaround Time: Normal / 24 Hour / Rush

Sample Date: 11/3/08

Sampler: MANU T. SCHMIDT

| Sample No. | Description/ Location | Analysis |
|----------------------------|---|----------|
| SMG 2801 11-3-08 01A | HVAC DUCT WOVEN CANVAS WRAP. OVER FIBER GLASS, BASKETBALL COURT DECK | PLM. |
| 02B | WEST | |
| 01C | EAST | |
| 02A | WEST | |
| 03A | 4" COVE MASTIC, YELLOW, BASKETBALL COURT PLASTER LAYERS | |
| 03B | 106A STG RM. | |
| 03C | HALLWAY FIRE CLOSET | |
| 04A | HALLWAY. 12" VFT WHITE WITH BLACK SPECKS AND YELLOW MASTIC 106A | |
| 05A | GRAY FLOOR TILES WITH BROWN MASTIC (UNDERNEATH 04A) 106A. | |
| 06A | 12" VFT, YELLOW MOTTLED AMBER MASTIC, RM 105 | |

Please sign this form below acknowledging sample receipt and return executed form with laboratory reports.

| | |
|-----------------------------|-------------------------------------|
| Sent by: <u>[Signature]</u> | Received by: <u>[Signature]</u> |
| Date sent: <u>11/3/08</u> | Date received: <u>11-4-08 15:14</u> |

Sent via Federal Express Air Bill:

Hand delivered



ACUMEN

INDUSTRIAL HYGIENE INC

1032 IRVING ST. - BOX 922 SAN FRANCISCO CA 94122

TEL 415 242 6060 FAX 415 242 6006

WWW.ACUMEN-IH.COM

BULK CHAIN OF CUSTODY FORM

116017

Project No. SMG 2801

Job Site: VA Palo Alto

Laboratory: MICRO

Location: BUILDING 23

Turnaround Time: Normal / 24 Hour / Rush

Sample Date: 11/3/08

Sampler: MARK T. SCHMIDT

| Sample No. | Description/ Location | Analysis |
|-----------------------------------|---|----------|
| 11 SMG 2801 10-31-08 07A | 2'X4' DROP-IN ACOUSTICAL CEILING PANELS, WITH SMALL RANDOM HOLES 109 | PLM. |
| 12 07B | ↓ 109 | |
| 13 07C | ↓ 109 | |
| 14 08A | MORTAR ON 5" CERAMIC TILE GRAY COVE RESTROOM 103 | |
| 15 09A | GROUT ON ABOVE " " ↓ " | |
| 16 10A. | GROUT ON 4" CERAMIC TILE, ON WALLS 103 | |
| 17 11A | MORTAR ON " " ↓ " | |
| 18 12A. | GROUT ON 4" CERAMIC TILE JANITOR'S CLOSET, RM 102 | |
| 19 13A | MORTAR ON " " ↓ " | |
| 20 14A | GROUT ON 1" BEIGE CERAMIC TILE STEPS AT SWIMMING POOL. | |

Please sign this form below acknowledging sample receipt and return executed form with laboratory reports.

| | |
|-----------------------------|-------------------------------------|
| Sent by: <u>[Signature]</u> | Received by: <u>[Signature]</u> |
| Date sent: <u>11-4-08</u> | Date received: <u>11-4-08 15:14</u> |

Sent via Federal Express Air Bill:

Hand delivered



ACUMEN

INDUSTRIAL HYGIENE INC

1032 IRVING ST. - BOX 922 SAN FRANCISCO CA 94122

TEL 415 242 6060 FAX 415 242 6006

WWW.ACUMEN-IH.COM

BULK CHAIN OF CUSTODY FORM

119017

Project No. SMG 2801

Job Site: VA PALO ALTO

Laboratory: MICRO

Location: BUILDING 23

Turnaround Time: Normal / 24 Hour / Rush

Sample Date: 11/3/08

Sampler: MARK T. SCHMIDT

| Sample No. | Description/ Location | Analysis |
|----------------------------------|--|----------|
| 21 SMG 2801 11-3-08 15A | MORTAR ON 1" BEIGE CERAMIC TILE STEPS AT SWIMMING POOL. | PLM |
| 22 16A | SHEETROCK COMPOSITE, SWIMMING POOL, - SW CORNER | |
| 23 16B | NE | |
| 24 16C | WEST CENTER | |
| 25 17A | GROUT ON 6" CERAMIC TILE CREAM ON COVE SWIMMING POOL, SW. | |
| 26 18A | MASTIC ON ABOVE " " " (ANALYZE MASTIC ONLY) | |
| 27 19A | WINDOW PUTTY, BUILDING EXTERIOR SW | |
| 28 19B | WEST CENTER | |
| 29 19C | NW. | |
| 30 20A | BLACK TAR PAPER WRAP OVER F/G INSULATED PIPES IN STEAM TUNNEL, 23 | |

Please sign this form below acknowledging sample receipt and return executed form with laboratory reports.

| | |
|-----------------------------|-------------------------------------|
| Sent by: <u>[Signature]</u> | Received by: <u>[Signature]</u> |
| Date sent: <u>11-3-08</u> | Date received: <u>11-4-08 15:14</u> |

Sent via Federal Express Air Bill:

Hand delivered

MICRO ANALYTICAL LABORATORIES, INC.**LEAD IN PAINT - FLAME AAS (EPA 7420)**

1092

Paul Spillane

Acumen Industrial Hygiene, Inc.

1032 Irving Street, #922

San Francisco, CA 94122-2216

PROJECT:

VA PALO ALTO

BUILDING 23

PROJECT NO. SMG2801

Micro Log In **118018**

Total Samples 7

Date Sampled 11/03/2008

Date Received 11/04/2008

Date Analyzed 11/04/2008

| Sample ID | | Weight Percent | Lead Concentration mg/kg (ppm) | Reporting Limits |
|----------------------------|--|----------------|-----------------------------------|--------------------|
| Client: SMG2801-11308-01PB | Lab: 118018-01 OFF WHITE PAINT CONCRETE WALL HALL AT RESTROOM 103 | 0.06% | 619 | 0.01 % 53 mg/kg |
| Client: SMG2801-11308-02PB | Lab: 118018-02 OFFICE WHITE PAINT ON CONCRETE COLUMN AND WALLS BASKETBALL COURT - WEST | | | |
| Client: SMG2801-11308-03PB | Lab: 118018-03 GRAY PAINT ON CONCRETE FLOORS AND COVE - HALLWAYS | 0.08% | 785 | 0.01 % 77 mg/kg |
| Client: SMG2801-11308-05PB | Lab: 118018-04 CREAM PAINT ON FLOORS AND COVE ROOM 110 LOWER | | | |
| Client: SMG2801-11308-11PB | Lab: 118018-05 INSTITUTIONAL GREEN PAINT ON SHEETROCK WALL - SWIMMING POOL AT SOUTHWEST | < 0.01% | < 76 | 0.01 % 76 mg/kg |

Technical Supervisor:

Tess Tagorda, Chemistry Supervisor

11/4/2008

Date Reported

Analyst:

LN

AIHA ELLAP Accredited Laboratory, ID #101768. Samples are analyzed by Flame Atomic Absorption Spectrometry (AAS). U.S. EPA SW-846 Method 7420 is used for the instrumental analysis. Nitric acid and hydrogen peroxide digestion procedures are based on ASTM E-1645. Unless otherwise indicated on this report, all required Quality Control samples have been determined to be in control prior to releasing these analytical results. Unless otherwise stated in this report, all samples were received in acceptable condition for analysis. This report must not be reproduced without the approval of Micro Analytical Laboratories, Inc., and pertains only to the samples analyzed. Unit explanations: mg = milligrams; kg = kilograms; ppm = parts per million. N/A = Not Applicable.

5900 HOLLIS STREET, SUITE M, EMERYVILLE, CALIFORNIA 94608 - (510) 653-0824

MICRO ANALYTICAL LABORATORIES, INC.**LEAD IN PAINT - FLAME AAS (EPA 7420)**

1092

Paul Spillane

Acumen Industrial Hygiene, Inc.

1032 Irving Street, #922

San Francisco, CA 94122-2216

PROJECT:

VA PALO ALTO

BUILDING 23

PROJECT NO. SMG2801

Micro Log In **118018**

Total Samples 7

Date Sampled 11/03/2008

Date Received 11/04/2008

Date Analyzed 11/04/2008

| Lead Concentration | | | |
|--|----------------|-------------|--------------------|
| Sample ID | Weight Percent | mg/kg (ppm) | Reporting Limits |
| Client: SMG2801-11308-12PB Lab: 118018-06 EXTERIOR PAINT - OFF WHITE ON CONCRETE | 0.01% | 109 | 0.01 % 73 mg/kg |
| Client: SMG2801-11308-13PB Lab: 118018-07 OFF WHITE PAINT ON LOCKER ROOM WALLS | < 0.01% | < 74 | 0.01 % 74 mg/kg |

Technical Supervisor: _____

Tess Tagorda, Chemistry Supervisor

11/4/2008

Date Reported

Analyst: _____

LN

AIHA ELLAP Accredited Laboratory, ID #101768. Samples are analyzed by Flame Atomic Absorption Spectrometry (AAS). U.S. EPA SW-846 Method 7420 is used for the instrumental analysis. Nitric acid and hydrogen peroxide digestion procedures are based on ASTM E-1645. Unless otherwise indicated on this report, all required Quality Control samples have been determined to be in control prior to releasing these analytical results. Unless otherwise stated in this report, all samples were received in acceptable condition for analysis. This report must not be reproduced without the approval of Micro Analytical Laboratories, Inc., and pertains only to the samples analyzed. Unit explanations: mg = milligrams; kg = kilograms; ppm = parts per million. N/A = Not Applicable.

5900 HOLLIS STREET, SUITE M, EMERYVILLE, CALIFORNIA 94608 - (510) 653-0824



ACUMEN

INDUSTRIAL HYGIENE INC

1032 IRVING ST. - BOX 922 SAN FRANCISCO CA 94122

TEL 415 242 6060 FAX 415 242 6006

WWW.ACUMEN-IH.COM

LEAD

BULK CHAIN OF CUSTODY FORM

Project No. SMG 2801 AA PAINT

Job Site: VA PALO ALTO

Laboratory: MICRO

Location: BUILDING 23

Turnaround Time: Normal / 24 Hour / Rush

Sample Date: 11/3/08

Sampler: MANUEL T. SCHMIDT

| Sample No. | Description/ Location | Analysis |
|---------------------|--|-----------|
| SMG 2801 11-3-08 | OFF WHITE PAINT ON CONCRETE WALL | |
| 01PB | HALL AT RESTROOM, 103 | LEAD (01) |
| 02PB | OFF WHITE PAINT ON CONCRETE COLUMN | (02) |
| 03PB | AND WALLS, BASKETBALL COURT WEST | (03) |
| 04PB | GRAY PAINT ON CONCRETE FLOORS | |
| 05PB | AND COVE, HALLWAYS | (04) |
| 06PB | 6"X11" LIGHT YELLOW, CERAMIC WALL | |
| 07PB | TILES, LOCKER, 100 | |
| 08PB | CREAM PAINT ON FLOORS AND COVE | |
| 09PB | RM 110 LOCKER | |
| 10PB | 5" CERAMIC TILE, AT COVE, GRAY | |
| 11PB | RESTROOM | |
| 12PB | 4" CERAMIC TILE, PART OF WALL | |
| 13PB | UP TO 4 FEET, RR 103 | |
| 14PB | 4" CERAMIC TILE, ON WALLS, | |
| 15PB | JANITOR'S CLOSET RM 102 | |
| 16PB | 1" BEIGE, CERAMIC TILE ON FLOORS, | |
| 17PB | AT STEPS, SWIMMING POOL | |
| 18PB | 6" CERAMIC TILE, CREAM ON COVES, SWIMMING POOL, SW | |
| 19PB | INSTITUTIONAL GREEN GREEN PAINT ON SHEETROCK. | (05) |
| 20PB | WALL, SWIMMING POOL @ SW. | |
| 21PB | EXTERIOR PAINT, OFF WHITE ON CONCRETE | (06) |
| 22PB | OFF WHITE PAINT ON LOCKER ROOM WALLS | (07) |

Please sign this form below acknowledging sample receipt and return executed form with laboratory reports.

Sent by: [Signature] Received by: [Signature]

Date sent: 11/3/08 Date received: 11.4.08 15:14

Sent via Federal Express Air Bill:

Hand delivered

MICRO ANALYTICAL LABORATORIES, INC.

EPA SW-846 - LEAD TTLC

Page 1 of 2

1092
Paul Spillane
Acumen Industrial Hygiene, Inc.
1032 Irving Street, #922
San Francisco, CA 94122-2216

PROJECT:

VA PALO ALTO
BUILDING 23
PROJECT NO. SMG2801

Micro Log In **118019**
Total Samples 6
Date Sampled 11/03/2008
Date Received 11/04/2008
Date Analyzed 11/07/2008

| Sample ID | Lead Concentration (mg/Kg or ppm) | Reporting Limit (mg/Kg or ppm) | Comments |
|---|--------------------------------------|-----------------------------------|----------|
| Client SMG2801-11308-04PB Micro 118019-01 6" X 11" LIGHT YELLOW CERAMIC WALL TILES LOCKER 100 | < 9.7 | 9.7 | |
| Client SMG2801-11308-06PB Micro 118019-02 5" CERAMIC TILE - AT COVE GRAY RESTROOM | 10055 | 480.2 | |
| Client SMG2801-11308-07PB Micro 118019-03 4" CERAMIC TILE PART OF WALL UP TO 4 FEET RESTROOM 103 | 9212.4 | 480.4 | |
| Client SMG2801-11308-08PB Micro 118019-04 4" CERAMIC TILE - ON WALLS JANITORS CLOSET 102 | 8292.5 | 481.9 | |
| Client SMG2801-11308-09PB Micro 118019-05 1" BEIGE CERAMIC TILE ON FLOORS AT STEPS SWIMMING POOL | < 9.7 | 9.7 | |

Technical Supervisor: Tess Tagorda 11/7/2008 Analyst: AW
Tess Tagorda, Chemistry Supervisor Date Reported

AIHA ELLAP Accredited Laboratory, ID #101768. Samples are analyzed by FLAA or ICP in accordance with EPA Methods 3050B for Acid Digestion (SW 846, 1992 edition) and 7420 or 6010 for Analysis (SW-846, 1986 edition). Unless otherwise indicated on this report, all required Quality Control samples have been determined to be in control prior to releasing these analytical results. Unless otherwise stated in this report, all samples were received in acceptable condition for analysis. This report must not be reproduced without the approval of Micro Analytical Laboratories, Inc., and pertains only to the samples analyzed. Unit explanations: mg = milligrams; kg = kilograms; ppm = parts per million.

5900 HOLLIS STREET, SUITE M, EMERYVILLE, CALIFORNIA 94608 - (510) 653-0824

MICRO ANALYTICAL LABORATORIES, INC.

EPA SW-846 - LEAD TTLC

Page 2 of 2

1092
Paul Spillane
Acumen Industrial Hygiene, Inc.
1032 Irving Street, #922
San Francisco, CA 94122-2216

PROJECT:

VA PALO ALTO
BUILDING 23
PROJECT NO. SMG2801

Micro Log In **118019**
Total Samples 6
Date Sampled 11/03/2008
Date Received 11/04/2008
Date Analyzed 11/07/2008

| Sample ID | | Lead Concentration (mg/Kg or ppm) | Reporting Limit (mg/Kg or ppm) | Comments |
|---|--------------------|--------------------------------------|-----------------------------------|----------|
| Client | SMG2801-11308-10PB | 87 | 9.7 | |
| Micro 118019-06 6" CERAMIC TILE CREAM ON COVES - SWIMMING POOL SOUTHWEST | | | | |

Technical Supervisor: _____

Tess Tagorda, Chemistry Supervisor

11/7/2008

Date Reported

Analyst: _____ AW

AIHA ELLAP Accredited Laboratory, ID #101768. Samples are analyzed by FLAA or ICP in accordance with EPA Methods 3050B for Acid Digestion (SW 846, 1992 edition) and 7420 or 6010 for Analysis (SW-846, 1986 edition). Unless otherwise indicated on this report, all required Quality Control samples have been determined to be in control prior to releasing these analytical results. Unless otherwise stated in this report, all samples were received in acceptable condition for analysis. This report must not be reproduced without the approval of Micro Analytical Laboratories, Inc., and pertains only to the samples analyzed. Unit explanations: mg = milligrams; kg = kilograms; ppm = parts per million.

5900 HOLLIS STREET, SUITE M, EMERYVILLE, CALIFORNIA 94608 - (510) 653-0824



ACUMEN

INDUSTRIAL HYGIENE INC

1032 IRVING ST. - BOX 922 SAN FRANCISCO CA 94122

TEL 415 242 6060 FAX 415 242 6006

WWW.ACUMEN-IH.COM

LEAD

BULK CHAIN OF CUSTODY FORM

Project No. SMG 2801119079
~~119079~~
TTLICJob Site: VA PALO ALTOLaboratory: MICROLocation: BUILDING 23Turnaround Time: Normal / 24 Hour / RushSample Date: 11/3/08Sampler: MAHL T. SCHMIDT

| Sample No. | Description/ Location | Analysis |
|---------------------|---|----------|
| SMC 2801 11-3-08 | OFF WHITE PAINT ON CONCRETE WALL | |
| 01PB | HALL AT RESTROOM, 103 | LEAD |
| 02PB | OFF WHITE PAINT ON CONCRETE COLUMN AND WALLS, BASKETBALL COURT, WEST | |
| 03PB | GRAY PAINT ON CONCRETE FLOORS AND COVE, HALLWAYS | |
| 04PB | 6"X11" LIGHT YELLOW, CERAMIC WALL TILES, LOCKER, 100 | 01 |
| 05PB | CREAM PAINT ON FLOORS AND COVE RM 110 LOCKER | |
| 06PB | 5" CERAMIC TILE, AT COVE, GRAY RESTROOM | 02 |
| 07PB | 4" CERAMIC TILE, PART OF WALL UP TO 4 FEET, RR 103 | 03 |
| 08PB | 4" CERAMIC TILE, ON WALLS, JANITOR'S CLOSET 102 | 04 |
| 09PB | 1" BEIGE, CERAMIC TILE ON FLOORS, AT STEPS, SWIMMING POOL | 05 |
| 10PB | 6" CERAMIC TILE, CREAM ON COVES, SWIMMING POOL, SW | 06 |
| 11PB | INSTITUTIONAL GREEN GREEN PAINT ON SHEETROCK. WALL, SWIMMING POOL @ SW. | |
| 12PB | EXTERIOR PAINT, OFF WHITE ON CONCRETE | |
| 13PB | OFF WHITE PAINT ON LOCKER ROOM WALLS | |

Please sign this form below acknowledging sample receipt and return executed form with laboratory reports.

Sent by: [Signature] Date sent: 11/3/08

Received by: [Signature] Date received: 11-4-08 1514

Sent via Federal Express Air Bill:

Hand delivered

Appendix B

Previous Reports

Palo Alto Veterans Administration Hospital
Building 23
Palo Alto, CA

November 3, 2008

Acumen Project No SMG 2801B

Prepared For:

SmithGroup/The Design Partnership Associate
301 Battery Street, 7th floor
San Francisco, CA

VA Palo Alto - Results of Asbestos Visual Re-evaluation Survey - October 1999-January 2000

| Building | Wing | floor | NEW Designation | OLD Designation | Code | Orig In Insp Place | Quantity | Ccondition | Potential Damage | Suspect |
|----------|------|-------|-----------------|-----------------|------|-------------------------------------|----------|------------|---------------------|-------------------------------------|
| 23 | A | 1 | 23A101 | 23A101 | CT | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23A102 | 23A102 | P | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23A102 | 23A102 | WTM | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23A102 | 23A102 | FTM | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23A104A | 23A104A | WTM | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23A104A | 23A104A | P | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23A105 | 23A105 | PE | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23A105 | 23A105 | P | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23A105 | 23A105 | FT12 | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23A105 | 23A105 | FTM | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23A106 | 23A106 | P | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23A106 | 23A106 | CV | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23A106 | 23A106 | FT9 | <input type="checkbox"/> | 260 | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23A106 | 23A106 | FTM | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23A106 | 23A106 | CVM | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23A106 | 23A106 | PE | <input checked="" type="checkbox"/> | Yes 340 | | | <input type="checkbox"/> |
| 23 | A | 1 | 23A106A | 23A106A | FT9 | <input checked="" type="checkbox"/> | Yes 130 | | | <input type="checkbox"/> |
| 23 | A | 1 | 23A106A | 23A106A | P | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23A106A | 23A106A | FTM | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23A106B | 23A106B | P | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23A106B | 23A106B | FT9 | <input checked="" type="checkbox"/> | Yes 260 | | | <input type="checkbox"/> |
| 23 | A | 1 | 23A106B | 23A106B | FTM | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23A107 | 23A107 | FTM | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23A107 | 23A107 | WTM | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23A107 | 23A107 | PFV | <input checked="" type="checkbox"/> | Yes 96 | | | <input type="checkbox"/> |
| 23 | A | 1 | 23A107 | 23A107 | FL | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23A109 | 23A109 | CT | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23A109 | 23A109 | WTM | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23A109 | 23A109 | P | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23A110 | 23A110 | CT | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |

ACM Still in Place*

| Site | Building | Wing | Floor | NEW designation | OLD designation | Material | Quantity |
|------|----------|------|-------|-----------------|------------------|-----------------------|----------|
| PA | 7 | D | 1 | 7D131 | 7D131 | FLOOR TILE 12X12 | 275 |
| PA | 7 | D | 1 | 7D139 | 7D139 | FLOOR TILE 12X12 | 199 |
| PA | 7 | F | 1 | 7F124 | 7F124 LOBBY | FLOOR TILE 12X12 | 1900 |
| PA | 7 | F | 1 | 7F124A | 7F124 MEN BATH | FLOOR TILE 12X12 | |
| PA | 7 | F | 1 | 7F124B | 7F124 WOMEN BATH | FLOOR TILE 12X12 | |
| PA | 23 | A | 1 | 23A106 | 23A106 | PIPES & ELBOWS | 340 |
| PA | 23 | A | 1 | 23A106A | 23A106A | FLOOR TILE 9X9 | 130 |
| PA | 23 | A | 1 | 23A106B | 23A106B | FLOOR TILE 9X9 | 260 |
| PA | 23 | A | 1 | 23A107 | 23A107 | PIPE FITTING & VALVES | 96 |
| PA | 44 | A | 1 | 44A1 | 44A1 | FLOOR TILE MATIC | 500 |
| PA | 44 | A | 1 | 44A1 | 44A1 | FLOOR TILE 12X12 | 500 |
| PA | 48 | A | 1 | 48A100 | 48A100 | FLOOR TILE 12X12 | 373 |
| PA | 48 | A | 1 | 48A103 | 48A103 | FLOOR TILE 12X12 | 182 |
| PA | 48 | A | 1 | 48A105 | 48A105 | FLOOR TILE 12X12 | 648 |
| PA | 48 | A | 1 | 48A110 | 48A110 | FLOOR TILE 12X12 | 28 |
| PA | 48 | A | 1 | 48A112 | 48A112 | FLOOR TILE 12X12 | 195 |
| PA | 48 | A | 1 | 48A113 | 48A113 | FLOOR TILE 12X12 | 143 |
| PA | 48 | A | 1 | 48A118 | 48A118 | FLOOR TILE 12X12 | 126 |
| PA | 48 | A | 1 | 48A119 | 48A119 | FLOOR TILE 12X12 | 28 |
| PA | 48 | A | 1 | 48A121A | 48A121A | FLOOR TILE 12X12 | 90 |
| PA | 48 | A | 1 | 48A125 | 48A125 | FLOOR TILE 12X12 | 664 |

*Asbestos still in place based on original survey and visual re-inspection October 1999-January 2000. Materials NOT listed on this report should NOT be considered as free from asbestos, but should be tested prior to disturbance using an EPA approved method.

Monday, September 22, 2008

Page 20 of 24

K E L L C O

VA Palo Alto - Results of Asbestos Visual Re-evaluation Survey - October 1999-January 2000

| Building | Wing | floor | NEW Designation | OLD Designation | Code | Orig In Insp Place | Quantity | Ccondition | Potential Damage | Suspect |
|----------|------|-------|-----------------|-----------------|------|-------------------------------------|----------|------------|------------------|-------------------------------------|
| 23 | A | 1 | 23A110 | 23A110 | WTM | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23A110 | 23A110 | P | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23AEC | 23AEC | P | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23AFC | 23AFC | P | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23AGYM | 23AGYM | FL | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 40 | A | 1 | 40A BOILER ROOM | 40A BOILER ROOM | P | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 40 | A | 1 | 40A001 | 40A001 | CT | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 40 | A | 1 | 40A001 | 40A001 | CVM | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 40 | A | 1 | 40A001 | 40A001 | WT | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 40 | A | 1 | 40A001 | 40A001 | CV | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 40 | A | 1 | 40A001 | 40A001 | FTM | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 40 | A | 1 | 40A001 | 40A001 | CTM | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 40 | A | 1 | 40A001 | 40A001 | WTM | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 40 | A | 1 | 40A001 | 40A001 | FT12 | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 40 | A | 1 | 40A002 CANTEEN | 40A002 CANTEEN | FTM | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 40 | A | 1 | 40A002 CANTEEN | 40A002 CANTEEN | CV | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 40 | A | 1 | 40A002 CANTEEN | 40A002 CANTEEN | FT12 | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 40 | A | 1 | 40A002 CANTEEN | 40A002 CANTEEN | CVM | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 40 | A | 1 | 40A002 CANTEEN | 40A002 CANTEEN | P | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 40 | A | 1 | 40A003 | 40A003 | P | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 40 | A | 1 | 40A004 | 40A004 | CM | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 40 | A | 1 | 40A004 | 40A004 | P | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 44 | A | 1 | 44A1 | 44A1 | FT12 | <input checked="" type="checkbox"/> | Yes 500 | | | <input type="checkbox"/> |
| 44 | A | 1 | 44A1 | 44A1 | FTM | <input checked="" type="checkbox"/> | Yes 500 | | | <input type="checkbox"/> |
| 44 | A | 1 | 44A1 | 44A1 | P | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 48 | A | 1 | 41A131 | 41A131 | FGM | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 48 | A | 1 | 48A CLOSET 110A | | CV | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 48 | A | 1 | 48A CLOSET 110A | | CVM | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 48 | A | 1 | 48A CLOSET 110A | | P | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 48 | A | 1 | 48A CLOSET 110A | | FT12 | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |

VA Palo Alto - Results of Asbestos Visual Re-evaluation Survey - October 1999-January 2000

| Building | Wing | floor | NEW Designation | OLD Designation | Code | Orig In Insp Place | Quantity | Ccondition | Potential Damage | Suspect |
|----------|------|-------|-----------------|-----------------|------|-------------------------------------|----------|------------|---------------------|-------------------------------------|
| 7 | F | 1 | 7F143 | 7F143 | CM | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 7 | F | 1 | 7F143 | 7F143 | CT | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 7 | F | 1 | 7F143 | 7F143 | P | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 7 | F | 1 | 7F143 | 7F143 | CVM | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 7 | F | 1 | 7F143 LOBBY | 7F143 LOBBY | CV | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 7 | F | 1 | 7F143 LOBBY | 7F143 LOBBY | FTM | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 7 | F | 1 | 7F143 LOBBY | 7F143 LOBBY | P | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 7 | F | 1 | 7F143 LOBBY | 7F143 LOBBY | CVM | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 7 | F | 1 | 7F143 LOBBY | 7F143 LOBBY | FT12 | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 7 | F | 1 | 7F143 LOBBY | 7F143 LOBBY | CT | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 7 | F | 1 | 7F143A | 7F143A | CM | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 7 | F | 1 | 7F143A | 7F143A | CT | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 7 | F | 1 | 7F143A | 7F143A | CV | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 7 | F | 1 | 7F143A | 7F143A | CVM | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 7 | F | 1 | 7F143A | 7F143A | P | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 7 | F | 1 | 7F144 | 7F144 | P | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 7 | F | 1 | 7F144 | 7F144 | CVM | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 7 | F | 1 | 7F144 | 7F144 | CM | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 7 | F | 1 | 7F144 | 7F144 | CV | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 7 | F | 1 | 7F144 | 7F144 | CT | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | | 1 | 23C1 | | P | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | | 1 | 23C1 | | CT | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | | 1 | 23C1 | | PNT | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23 BASEMENT | 23 BASEMENT | PFV | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23 BASEMENT | 23 BASEMENT | P | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23 BASEMENT | 23 BASEMENT | PE | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23 BASEMENT | 23 BASEMENT | T | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23A101 | 23A101 | P | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |
| 23 | A | 1 | 23A101 | 23A101 | TRN | <input checked="" type="checkbox"/> | | | | <input type="checkbox"/> |
| 23 | A | 1 | 23A101 | 23A101 | CVM | <input type="checkbox"/> | | | | <input checked="" type="checkbox"/> |

Appendix C

Photographs

Palo Alto Veterans Administration Hospital
Building 23
Palo Alto, CA

November 3, 2008

Acumen Project No SMG 2801B

Prepared For:

SmithGroup/The Design Partnership Associate
301 Battery Street, 7th floor
San Francisco, CA



Photo 1

View of building 23 exterior west side with windows and paints



Photo 2

View main hallway with painted floors and walls



Photo 3

View of Room 103 restroom ceramic tiles



Photo 4

View of pool with ceramic tiles (on far steps in background) and at wall coves



Photo 5

View of PACM pipe insulation at cat walk/HVAC areas in basketball court, center



Photo 6

View of PACM pipe insulation at cat walk/HVAC areas in basketball court, at wall ladder



Photo 7

View of fiberglass pipe insulation at lower walls, basketball court



Photo 8

View of presumed lead containing ceramic wall tiles




Photo 9

View of lead containing ceramic wall tile at Janitor's closet Room 102



Photo 10

View of ACM black tar paper jacketing over fiberglass insulated pipes in steam tunnel spur

Appendix D

Sample Location Drawings

Palo Alto Veterans Administration Hospital
Building 23
Palo Alto, CA

November 3, 2008

Acumen Project No SMG 2801B

Prepared For:

SmithGroup/The Design Partnership Associate
301 Battery Street, 7th floor
San Francisco, CA

Figure 1

Asbestos Sample Location
Veterans Affairs Medical Center – Building 23
3801 Miranda Avenue (Palo Alto, CA)

October 31, 2008




Figure 2

Asbestos Sample Location
Veterans Affairs Medical Center – Building 23
3801 Miranda Avenue (Palo Alto, CA)

November 3, 2008




Figure 3

Lead Sample Location
Veterans Affairs Medical Center – Building 23
3801 Miranda Avenue (Palo Alto, CA)

October 28, 2008

